



Reduce float dust explosion hazards

Add an in-line wetted scrubber

▶ Did you know?

Float dust reductions of **>90%** can be achieved by adding an in-line wetted scrubber to an auxiliary section fan*

Coal mine operators can use this combination to reduce the possibility of a coal dust explosion in the return




Photo by NIOSH